


## QUOTATION

Name of work:- Replacement of faulty MCCB in LT panel feeding to 600KVAR APFC panel of Transformer No. 2 at Substation No. 4 with new 1250A MCCB.

S.No.	Description of item	Qty	Unit	Rate (in words & Figures)	Amount
1	Disconnecting and Dismantalling damaged pole fuse box/ Changeover Switch/main switch / MCCB/ Contactor /DB/KWH meter of any size from site and depositing in store I/c cartage etc. as reqd.	1.00	Each		
2	Providing and fixing of 3pole, 70KA, 415V DPX3 1600, MCCB 1250A, rating and breaking capacity MCCB with rotary handle in existing cubicle panel board including drilling holes in cubicle panel, making connections, etc. as required.make: legrand only.	1.00	Each		
<b>Total Rs.</b>					

  
अधिसाधी अधियता-विद्युत E.E. (Elect.  
संविद्युत, मातृप्रो संस्थान, कानपुर  
I.W.D., I.I.T., Kanpur  
