


N/ Repairing of 25 HP submersible pump sets for tube wells
W

SLNo	Description	Qty	Unit	Rate	Amount
1	Repairing of 25 HP submersible pump sets i/c rewinding of motor, replacement / repairing of motor bushes, oil seal, rotor sleeve U/L, thrust plate,, thrust bearing cable gromet, connecting cable, shaft, bowl bush, bowl assembly, distance sleeve, neck ring, impeller, necessary machining work etc. complete in all respect.	4.00	Each		
2	Add Gst @18%				
	Total				


(V. P. Singh)

Executive Engineer