


QUOTATION

Name of work - Repairing and servicing of ceiling fans installed at Old SBRA, New SBRA, RA tower, Old Sport complex and Hall-13 Mess as per enclosed complaints.

Description of Items	Qty	Unit	Rate (In words & Figures)	Amount
1 Rerinding of following fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rerinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismantling and refixing from normal/abnormal height and refixing as required. (Old burnt wire shall be reatin by the contractor.)				
a) Old model 48"/new model 56" (fan)	1.00	Nos.		
2 Overhauling of following fan of any size including bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/ split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.				
a) ceiling fan	113.00	Nos.		
3 Dismantling & refixing of any size fan from normal height				
a) ceiling fan	113.00	Nos.		
4 Supplying and fixing following capacity capacitor suitable for ceiling fan / exhaust fan / air-curtain etc.				
a) 2.5mfd	37.00	Nos.		
5 Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc.	8.00	Nos.		
6 Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.	113.00	Nos.		

Total Rs


राघवेंद्र सिंह
RAGHVENDRA SINGH
अधिकापी अभियंता (शि.) ए.ए. (Elect.)
संनिविदा, या.प. सं. सं. सं. सं. सं.
I.W.D., I. & E., Kurpur
