Quotation

Name of work:- Replacement of defective DGC-7 Genset controller for PROCOM of DG set 1x250KVA installed at Hall-12.

S.N	Description of item	Qty	Unit	Rate (In words & Figures)	Amount
1	Repairing / Repalcement of defective DGC-7 Genset controller for PROCOM of DG sets 250KVA as required complete	1.00	each		

Total Rs.

RAGHVENDRA STIGH
अधिशाधी अधियंता (वि॰) E.E. (Elect.
सन्ति॰वि॰, भा॰प्री॰ संस्थान कानपुर