


QUOTATION

Name of work - Rewinding / overhauling / repairing of ceiling fans in Visitor Hostel Extension Block A, B, C, D type 1 and residential area of north side of main drive as per enclosed complaints.

S.No.	Description of Items	Qty	Unit	Rate	Amount
(In words & Figures)					
1	Painting of ceiling fan in installed position with one or more coats of spray painting with synthetic enamel paint of approved brand and manufacture to give an even shade, including cleaning of surface with detergent etc. as required.	4.00	Nos.		
2	Rewinding of following fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismantling and refixing from normal/abnormal height and refixing as required. (Old burnt wire shall be reatin by the contractor.)				
a)	New model 48"	16.00	Nos.		
3	Overhauling of following fan of any size including bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/ split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.				
a)	ceiling fan	95.00	Nos.		
4	Supplying and fixing following capacity capacitor suitable for ceiling fan / exhaust fan / air-curtain etc.				
a)	2.5mfd	45.00	Nos.		

5	Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc.	30.00	Nos.	
6	Dismantling & refixing of any size fan from normal height			
a)	ceiling fan	81.00	Nos.	
7	Balancing of ceiling fan blade of any size including making suitable shape of twisted blades at site.	10.00	Nos.	
8	Supply of ball bearings as following size.			
a	Ball bearing 6201 (NBC-make)	25.00	Nos.	
b	Ball bearing 6202 (NBC-make)	25.00	Nos.	

Total Rs


राघवेंद्र सिंह
RAGHVENDRA SINGH
 अधिशासी अभियंता (वि०) E.E. (Elect.)
 ज०नि०दि०, वा०मै० संस्थान, कानपुर
 I.W.D., I.I.T., Kanpur
