


QUOTATION

Name of work:- Replacement of faulty AMF panel controller relay of 750KVA DG set installed at Substation no. 9 and replacement of 400A contactor in AMF panel of 250KVA DG set installed at DG house no. 1.

S.N	Description of item	Qty	Unit	Rate (In words & Figures)	Amount
1	Replacement of defective DGC-7 Genset controller relay for PROCOM of DG sets 750KVA as required complete as directed by Engineering In charge.	1.00	each		
2	Supplying, fixing, testing and commissioning of following contactor including dismantling of existing defective and damaged contactor etc as required complete as directed by Engineering In charge.				
a	400 Amp 4 pole AF 265-40	1.00	each		
Total Rs.					<hr/> <hr/>


अधीक्षक अभियन्ता / S.E.
सोनिकविठो (I.W.D.)
भाउप्रौठ सस्थान, कानपुर
I.I.T., Kanpur

